

QTI Technical Memo

Date: DEC. 10, 2018

SR#: 03775373

Customer: Longcheer Telecommunication Limited

Customer Project: L6250

SW Build ID: mpss.ta.2.3.c1-00640-8953_GEN_PACK-2

Subject: SIP error code not report to AP

Problem Description

In TA2.3, SIP error code not report to AP side. We have a FR to report the SIP error code from IMS to AP side. The FR is not merged in TA2.3, but exit in TA3.0, so customer should move to TA3.0 to get this FR.

Conclusion:

Pls customer move to TA3.0 to get this FR, which report SIP error code to AP side.